





Research and Resources on Traumatic Occupational Incidents



March 12, 2015

Presenters

- Jennifer Flood, Ombudsman for Injured Workers
- Illa Gilbert-Jones, OR-FACE Program Manager/Field Investigator
- Mike Riffe, Accident Investigator, OR-OSHA

Agenda

- Injured Workers Ombudsman
 - Role
 - Resources
 - Case examples
- OR-FACE
 - Mission
 - Case example
 - Resources
- OR OSHA Accident Investigator
 - Accident cases and models



Ombudsman for Injured Workers

- Role
- Resources
- Case Example

Number of compensable fatalities¹ by industry², Oregon, 2010-2014 (preliminary as of March 3, 2015)

INDUSTRY (NAICS code)	Work-related compensable fatalities				
	2010	2011	2012	2013	2014
Agriculture, forestry, fishing (11)	4	7	5	9	4
Logging (113)	3	4	3	6	3
Mining (21)		2	1 50 1	0	1
Utilities (22)		1	2	-	
Construction (23)	1	3	5	7	3
Manufacturing (31-33)	3	3	4	2	2
Wholesale trade (42)	1	2			2
Retail trade (44-45)	1	2 - 2	2	2	3
Transportation and warehousing (48-49)	3	4	5	4	4
Truck transportation (484)	3	3	4	4	3
Information (51)		1	4	7	-
Finance and insurance (52)		3 -2 -1	F 75 0	-	
Real estate, rental and leasing (53)	D. T. Y.	2 2 1	3 75 0	3	1
Professional, scientific, tech svcs. (54)		4	1.2.	1	4.
Management of companies (55)	1 - 1 - 1	12	1 74- 1		4
Admin, supp, waste mgmt, remed (56)	-	1	2 4	1	3
Educational services (61)	(-2-1		1 5 1		1
Health care and social assistance (62)		1	1	1	
Arts, entertainment and recreation (71)		-	1	¥	1
Accommodation and food svcs (72)			3	1	1
Other services (81)		2	1	1	. 1
State and local government (OWN 20, 30)	3	3	3	2	5
Total	17	28	30	30	31

Compensable fatalities are claims, accepted by insurers, arising from a fatal occupational injury or disease that entitles workers, their survivors, or both to compensation.

Data exclude deaths of workers not subject to Oregon workers' compensation coverage, such as workers who were selfemployed, worked in Oregon for out-of-state employers, city of Portland police and fire employees, or federal employees.

Note: Dashes indicate no claims were received.

Counts for 2014 are preliminary and subject to change as source data for fatalities are received throughout the year. Fatality counts for previous years are final.

Data are based on the date the Department of Consumer and Business Services received notification that the fatality claim was accepted, which may be different than the date of injury or the date of death.

Source: Central Services Division, Oregon Department of Consumer and Business Services, March 3, 2015

North American Industry Classification System (NAICS), 2002 Edition



Department of Consumer and Business Services

Office of Ombudsman for Injured Workers 350 Winter St. NE, Room 160 P.O. Box 14480 Salem, OR 97309-0405 503-378-3351 or 800-927-1271 Fax: 503-373-7639 www.oregon.gov/DCBS/OIW

Oregon Workers' Compensation Benefits for Accepted Fatal Injuries

New Benefit Levels effective July 1, 2014

Benefits apply to Oregon injured workers subject to ORS Chapter 656 with dates of injury on or after July 1, 2014. Benefits are not due until claim acceptance.

Final Disposition & Funeral expenses:

\$17,767.60 (unpaid balance paid to worker's estate)

Spouse & Children: combined max = \$5,152.48 a month

Spouse = \$2,576.43 a month

Children (up to age 18, or 23 if attending higher education)

Child – dependent on surviving spouse = \$386.45 a month

Child - NOT dependent on surviving spouse = \$966.11 a month

Child - no surviving spouse = \$966.11 a month

Children age 18 to 23 – without a living parent \$2,576.43 a month while attending higher education

Other Dependents: combined max = \$386.45 a month

"Other Dependents" are named relatives who were dependent, in whole or in part, on the worker. Benefit is based on 50% of average monthly support actually received from the worker during the previous 12 months.

For questions regarding Oregon Workers' Compensation:

Jennifer Flood, Ombudsman for Injured Workers Dept of Consumer & Business Services Toll-free: 800-927-1271 ext. 7031 Local (Salem): 503-947-7031 Email: jennifer.r.flood@state.or.us




Mission

- Prevent traumatic work-related deaths in Oregon through
 - Surveillance
 - Targeted investigation,
 - Assessment
 - Outreach




Surveillance 2012






OR-FACE Worker fatalities in Oregon (2003-2013) **Total number of cases by year**





Worker fatalities in Oregon (2003-2013) Top 10 industries in total number





Investigations

Published (2013-2014)

- Experienced journeyman machinist killed while operating an engine lathe
- 2. Millwright fatality involving a hydraulic accumulator
- Timber faller killed while working under a hung tree limb
- 4. Collapsed roof trusses kill carpenter foreman

Guiding Principles

- Maintain confidentiality
- Provide facts
- Provide best practice recommendations (beyond regulatory requirements)




Keywords: Construction, Truss collapse, Fall [NAICS=236117] Publication Date: July 2014 Oregon FACE Program OR 2013-27-1



Fatality Investigation Report

OR 2012-18-1

Experienced Journeyman Machinist Killed While Operating an Engine Lathe



Mechanic

- 69 years old
- Journeyman with 30+ years of experience
- New to this shop

Worksite

- Machine shop
- Different models of machine lathes
- Six employees
- New owner

Unfinished part



Finished part




Part

- Eccentric shaft (off set centers)
- Steel stock
- Short shaft vs long shaft
- Radius transition

Work practice

- Gloves to handle steel stock
- Emery cloth to smooth radius transition
- Clothing long sleeved thermal shirt underneath cut sleeved sweatshirt



Engine lathe involved in incident

- 40 years old
- Manufactured in Taiwan in 1968
- 1 unguarded chuck
- 2 red "inch" button



Other engine lathe in shop

- 16 years old
- Manufactured in England in 1996
- 3 guarded chuck
- 4 red emergency stop

The incident

- Machinist turning his first short length (30.5 inches long)
 eccentric shaft (workpiece), had completed a few longer shafts
- Rough machining completed (7 hours)
- Part slipped in chuck jaws and had damaged end
- Told to smooth radius transition using emery cloth then reverse part
- Spindle speed set at 590 rpm (supervisor sets speed at 330 rpm)
- Operator of nearby CNC machine heard "winding up" sound and pushed red button repeatedly
- Gloves found on equipment

CAUSE OF DEATH

Lacerating and penetrating injuries of neck and chest

Contributing Factors

- Defective tool (bent chuck key)
- New employee, high expectations, minimal guidance
- Clothing cut-off sleeve sweatshirt
- New task short piece
- Older equipment (different safety features)

Recommendations

- 1. Employers should establish, <u>communicate and</u> <u>enforce a clothing policy</u> specific to the work environment and particularly for machine operators.
- 2. Employers should establish formal <u>training</u> on recognized <u>hazards</u>, <u>injury prevention</u> and <u>emergency procedures</u>, and to communicate expectations to adhere to safe practices and policies.
- 3. Supervision should <u>monitor</u>, reinforce safe behaviors, and <u>immediately correct unsafe behaviors</u> or conditions.

Recommendations Cont'd

- 4. Job hazard analyses should be conducted by operators and supervisors and should include a review of the manufacturer's equipment/operator's manual, machine labeling, color coding, etc., especially for legacy machines.
- 5. Employers should implement preventive maintenance and inspection processes for hazardous machines. Where necessary, employers should install, adjust, label and/or repair appropriate controls (e.g., machine guards, emergency stops).




Outreach

- Website
- Publications
- Interventions
- Presentations



Website






Annual Reports











- Published 18 months
- Abstract of cases
 - Based on report review
 - OSHA investigation
 - Police investigation
 - Medical examiner
 - Pathology
 - Toxicology
 - National Transportation
 Safety Board
 - US Coast Guard



Booklets










Interactive Maps (2003-2012)





Hazard Alerts

OR-FACE Fatality Alert

November 2003



#1 OR2003-36-01



#2 OR2003-37-01



#3 OR2003-37-01



Truck mounted pile driver presents fatal electrocution hazard

Fatal Fall Alert

Gravity Kills

In 3 years, 22 Oregon workers died in falls. Risk

increases greatly over age 35, and ac

Fall hazards are everywhere. Fa Please observe the following s

Recommendations

- Make sure ladder is in good cond and locks are secure. Set base 1/4 length from wall, supported at top rails extending 3-4 ft above disme
- . Three-point rule: Get a firm grip v of four limbs, especially in icy co
- · Beware losing your balance from unexpected release of a weight yo carrying or pulling, or from overre

Fatal Stories, 2003-2005

Store ladder A female retail clerk fell from the sixth str in a company storeroom, and died 5 days later. She sust the left knee and femur. The clerk was admitted to a loca she developed sepsis.

Icy lumber load A lumber yard worker was killed whe ft off a loaded semi-trailer. The worker placed an extensi the load and climbed to the top to strap it down. Ice had of plastic covering the load, and the worker apparently s

Roof exit A school custodian died after falling about 12 He used a fully extended extension ladder to access a roballs. The spring-loaded locks were not set properly, whi custodian to climb the ladder successfully, but the ladde he put his weight on it to return to the ground.

ELEVATED LEDGE

Concrete tank A construction worker died after falling concrete tank. The worker was removing concrete from a water treatment tank that was being dismantled, and was the fastening strip from the top edge. He was either ben kneeling to perform this task, and apparently lost his bal stood up to move to the next section.

Conveyor belt A miner fell 12 ft onto a concrete floor f of an elevated conveyor at a sand and gravel operation. day. The miner and two coworkers were installing a new The miner was standing on a crossbeam, pulling on a ro

OR -FACE Ore

One page

- **Bulleted** recommendations
- Abstract of similar cases

OR -FACE **Snag Hazard** Alert

From 2010 to 2013, 10 Oregon workers in the Logging and Forestry industries died after being struck by trees. Hung limbs and snags in trees are a recurring contributing factor to occupational fatalities among tree fallers in Oregon.

Please observe the following safety tips:

- . Scan for hung or snagged trees and limbs in your own and others' cutting st communicate with each other about these hazards
- · When faced with a hazardous situation, stop work and seek assistance from a cutting partner, or a more experienced worker.
- If a snag or hang-up is identified, after seeking assistance, work with your pa identify the best method for alleviating the hung limb, tree or snag (OR-OSH) working under a lodged tree or the cutting of a tree where another tree is lod
- . Employers should ensure that workers are trained and understand how to sa to snagged or hung limbs and other hazardous logging conditions.

Fatal Stories

Case 1: A 28-year-old self-employed tree cutter was killed after he was struck by a dislodged treetop and crushed between previously felled logs and underbrush. The victim had cut a small second growth tree, but it had hung up in another tree as it fell. He was attempting to fall another larger tree when the lodged tree broke free and fell on him

Case 2: A.51 year-old logger was killed after he was struck by a falling snag that was caught in the tree he was cutting. He was working on a steep hillside. and his partner was 250-300 yards away. His partner searched for the victim after he had not heard the victim's saw in 40 minutes. He found the victim dead with a tree on top of him. The victim had 25 years of logging expenence.

Case 3: A 48-year-old tree faller was killed after a snagged tree fell on top of him. The victim was working as an independent contractor cutting trees He had just felled a large tree on a hillside, which uprooted a rotten tree on its way down. The rotter

tree hit the victim from behind and pi underneath. He was working alone a incident. The victim died at the scen

Case 4: A 11-year-old logger was k was struck in the back by a falling tre was working as part of a two person cutting alder trees on private logging minute intervals, each worker would to listen for their partner's saw. The performed this safety check, but did partner's saw. He went to check on to found him face down with a 12-inch foot long treetop across his back. Ap the victim cut down his last tree it or nearby tree, which caused the top of to break apart and fall over onto the was conscious when his partner four on his way to the hospital. He died from

Oregon Fatality Assessment and Control Ev 503-494-2281 www.ohsu.eduli

OR FACE Crab Fishing Hazard Alert

deaths off the US West Coast were caused by drowning. Dungeness crab fisheries had the highest number of fatalities with a rate of 310 per 100,000 full-time equivalent workers. Falls overboard accounted for 24% of all fatalities. None of the victims of falls overboard were wearing personal flotation device.*



- · Wear personal flotation device whenever on deck and every time the bar is crossed
- Train crew on man-overboard procedures and practice at least monthly
- · Use the most current weather forecasts and bar information
- Use personal locator beacons that are water activated for visibility
- · Get vessel stability evaluations to aid in loading properly Utilize Coast Guard vessel inspections

Fatal Stories

Case 1: The 43-year-old crab boat captain survived when the vessel he was operating capsized but was pushed up on the letty. Two crew members (44 and 55 years-old respectively) died after being swept overboard. None of the crew wore life vests or personal floatation devices, nor was there time to do so when the waves hit. They were attempting to cross the bar in rough seas. The victims were part of a three person crew that was preparing for the opening of crab season. When the boat was attempting to As it tried to exit it got sideways to the breakers, one end was pushed up and the next wave turned

was preparing for the opening of crab season. The boat was roughly three miles out from a bay when it became unstable and began to tilt. Before the crew could determine the problem the boat was hit by a large wave and tipped on its side. The two deckhands were able to put on personal flotation devices and swim to a nearby boat where they were pulled onboard. The captain was apparently trapped inside the wheelhouse when the boat fully capsized and he was unable to escape.

Case 3: A 38-year-old commercial fisherman was killed when his fishing boat capsized. The 21-foot boat capsized in high waves after an engine failure. Witnesses called for help and reported that there were two men on the boat. Initial responders w



Blogs



Toolbox talks are a common form of safety communication, especially in construction but they have been used as

daily pre-shift meetings in general industry. OR-FACE has treated several toolbox talls guides and retently

similar modent. On the other side, are instructions for leading the toolbox talk, a nametive of the incident

understanding the vey elements of the incident. At the bottom of the line drawing are key actions to prevent a

bulleted items that reiterate the key prevention actions and a flat of questions to facilities a discussion on pursuit

The overarching goal of these toolbox tall guides is to provide supervisors leaders with documents to increase

interaction and positively influence safe behaviors. The formet uses evidence-based safety communication

published four. These two-page documents are based on information gathered from Oregon famility investigations. One side of the footbook talk is a simple line drawing for valuing from a distance and for each in

practices, unsafe conditions, and commitment to air action plan

principles and real-world (Oregon) relatable events.

OR-FACE presents at logging and construction safety events



Recent Comments

Annua Trimming on Inhabitar Control & Staying II

reason or Tenning Princip Winness Transfer to

to see Warried Victoria Withhard 1976-1276 to Zin

Aum Machingo on May Gui Scottoner Marc I

Clark Vermillion thanks Illa Gilbert-Jones on behalf of the CSS.

Oregon." You can find both presentations and resources on the OR-FACE website.

Submitted by Illa Gilbert-Jones, CIH, CSP, Oregon FACE Program Manager/Field Investigator.

Oregon Fatality Assessment and Control Evaluation (OR-FACE) presented at the January meetings of the Washington Contract Loggers Association (WCLA) and the Portland Construction Safety Summit (CSS).

Jeffrey Wimer, OR-FACE Safety Consultant and Oregon State University Manager of Student Logging Program, presented OR-FACE logging adts and resources to over 500 attendees at the annual WCLA Safety Conference held near Olympia on January 17. The resources created by Jeff and OR-FACE will contribute to the Washington State Logger Safety Initiative. The Oregon forestryllogging industry had 91 FACE cases from 2003-2013 and ranks second in the highest number of total fatalities.

The Oregon construction industy ranks third with 84 fatal occupational cases. Illa Gilbert-Jones presented OR-FACE construction data and resources to 40 members at the CSS January 20 meeeting. Construction and logging are high risk industries in Oregon and providing outreach information to these two industry groups aligns with the OR-FACE mission to "prevent occupational fatalities through surveillance, tergeted investigation, assessment and outreach associated with traumationovir-related deaths in





Preventing Construction Fatalities: The Toolbox Guide Initiative

OR-FACE PSU Occupational Health Psychology Hoffman Construction Fortis Construction SAIF Corporation



PLAN

ahead to get the job done safely.

PROVIDE

the right equipment.

TRAIN

everyone to use the equipment safely.



Tool Box Talk Guides: *Evidence-Based Structure*

FRONT: Scripted Story

BACK: Line Drawing

Toolbox Tall Load of Lumb

INSTRUCTIONS side facing you High urgency alert word in color

ipt with instructions



Our safety talk todal, framer from another company who died when a load of lumber fell on him. He was on a ladder to

house while a roug bundle of lumber to weighed at least 60 maximum possible tipped over. The lu the victim's head ar against the ladder. he fell to the first flo probably died from

Line drawings increase understanding and viewing distance

Top 3 preventive acti

So here are sor

happening where we work.

- Never exceed the load or extension limits of a lift or crane. You should be trained before you operate a lift or crane, and I can make sure you get the training.
- Never work direct are required to b
- Use a spotter an advance, and to

ASK: "Does any Pause for

END WITH ACT

- END WITH AC
- "Are there any their limits?"
- · "Does anyone have ideas for improving our communication systems?"
- "What do you all do to make sure people are not under loads being moved?"
- Discuss a similar situation at your current site.
- · Express your commitment to training people for each machine they operate.
- Commit to follow-up at the next safety talk.


Prompts for discussion and correcting hazards

- Never exceed load or extension limits of a lift or crane
- Use a spotter and communication system to prevent lifts over workers
- Never work directly under a load


3 Field Studies (sample findings)

Study 1: Current Pre-Shift Practices (n=28)

My company conducts pre-shift talks/briefings




frequency 28% weekly 32% daily



3 Field Studies (sample findings)

Study 2: Image Viewing Distances (n=30)









Study 3: Field Test (n=119)

Supervisors

Talk with FACE report

VS.


Talk with
Tool Box
Guide

Preferred 3:1


Workers

- Reactions
- Behavioral intentions
- Preference

Similar positive ratings









Proposed Projects

Mobile system to promote and

evaluate

toolbox talks

hazard alerts






Proposed Projects

- Preventing falls in residential construction
 - Identify Participants
 - Homebuilders Association
 - SAIF Corporation
 - Study
 - Experience in recent serious (non-fatal) fall from elevation will increase contractors participation in surveillance survey
 - Small grants program to supply fall prevention equipment and training.



Other Resources

- Oregon Institute of Occupational Health Sciences
 - Safety toolbox talks
 - Online videos
 - Newsletter
 - Blog







Accident Investigator

Mike Riffe, Fatality Investigator
Portland Field Office
OR-OSHA

In Memory Of



Mike Riffe, Fatality Investigator
Portland Field Office
OR-OSHA



The Tower


- Approx. 250 feet tall in three sections.
- Includes controls and switchgear in lower level.
- Approximately190' single span ladder from second level to yaw deck

The Nacelle

- Houses transmission and generator
- Includes disc brake with locking pins
- Weight approx. 82 tons


The Hub

- Weight approximately 25 tons
- Hub entry ports
- Pitch safety valves



The Assembled Turbine

- Approximately 141.9 tons balanced on top of tower
- Unit designed for blades to rotate between 14 and 16 rpm turning generator between 1400 and 1600 rpm
- Output up to 2.3 megawatt @ 600 VAC
- Yaw keeps unit pointed into the wind
- Pitch adjusts blade angle to control speed





Looking up toward second platform—inside tower




Rotor Locking Pin




Hub Entry Port Cover in Nacelle



Hub Entry





Closing one of the three pitch safety valves in the hub

The crew

- Thomas technical advisor 7 years experience in wind energy on temporary assignment from Germany.
- William apprentice wind technician helped with construction - 7 days experience in turbine maintenance.
- Chad apprentice wind technician 1 ½ months experience.
- Dustin apprentice wind technician first day on the job.
- Nick site manager 1 $\frac{1}{2}$ months with company 3 years prior experience as technician on other brands of turbines.

The process

- 500 hour service
- Blade pitch calibration
- Tower section bolt torque
- Remove tools

August 25, 2009

- 7:00 am tailboard safety meeting Chad, Dustin, William and Nick.
- 7:43 am Chad, Dustin and William shut down turbine W1 and began service.
- Approximately 11:00 am Chad and William enter hub and perform blade calibration – leave and reseal hub entry port.
- 12:30 pm lunch break in nacelle. Nick, working in the office goes home for the day.
- 1:00 pm Dustin and William go down tower to torque tower bolts, Chad stays in tower to finish clean-up.
- 1:30 pm Chad discovers cell phone is missing calls down to William and Dustin to call phone.
- 2:16 pm- data recorder indicates blades pitched to -2 degree position.
- 3:59 pm William in top section of tower climbing down Dustin on the ground in the pickup Chad in tower, releases service brake.
- 4:04 pm collapse.











Vehicle Operations

Energy Isolation and Control (LOTO)



Vehicle Operations









Celorie Brothers



Commercial Motor Vehicles


Brakes





Construction Power Line Contact







Construction Material Handling




Construction Bracing of Structures






Building Component Safety Information (BCSI)

Guide to Good Practice for Handling, Installing, Restraining and Bracing of Metal Plate Connected Roof Trusses




Building Component Safety Information (BCSI)

Guide to Good Practice for Handling, Installing, Restraining and Bracing of Metal Plate Connected Roof Trusses



Building Component Safety Information (BCSI)

Guide to Good Practice for Handling, Installing, Restraining and Bracing of Metal Plate Connected Roof Trusses






OAR437-003-0085

 An unimpaired horizontal clearance of not less than 3 feet shall be maintained between the rotating superstructure of any mechanical equipment and any adjacent object or surface. If this clearance cannot be maintained, barricades shall be installed to isolate the hazardous area.







Missing Cover / Fastener

No Safety Bolt









MODEL NUMBER MAN4 - 48D

WEIGHT

SERIAL NUMBER 21953

3145

4' HIGH X 8' LONG

SOIL	MAX DEPTH	PSF	SOIL DESCRIPTION	
TYPE A	120 Feet	3000	Stiff Cohesive Soil, 25 PSF per foot, clay, sitty clay, clay loarn with unconfined compressive strength of 1.5 ton per square foor or greater. See note 7.	
TYPE B	66 Feet	3000	Medium Cohesive to granular soil, 45 PSF per foot of depth. Clay with unconfined compressive strength greater than 0.5 TSF but less than 1.5 TSF. Cohesionless gravet, silt, silt loam or sandy leam. See note 8.	
TYPE C	50 Feet	3000	Soft Cohesive to Saturated Soil, 60 PSF per loot of depth. Clay with unconfined compressive strength tess than 0.5 TSF, saturated sand, clay or fractured rock that is not stable. See notic 9.	

LIMITATIONS

- Soil above shield must be sloped according to OSHA Subpart P. Stope must begin no less than 16" below the top of shield
- 2) Shield may be suspended no more than 2 feet above bottom of the Irench and only if there is no possible loss of soil from behind or below bottom of shield.
- 3) The sides of the excavation shall be cut vertical and narrow to prevent lateral movement of the Manhole Shield. If necessary, backfill around the Manhole Shield to a height sufficient to prevent lateral movement.
- Repairs and modifications must first be approved by manufacturer or moistened professional engineer
- Shields may be stacked as long as each is rated to the depth it is used and manufacturer approved stack connections are utilized.
- 6) Surcharge loads have not been included in the above depth ratings. The allowable working depth of the shield must be reduced to account for any surcharge loading which occurs within the influence line of the shield.
- 7) Not Type A if lissured. Subject to vibration, previously disturbed or part of a sloped layered system where layers dip into excavation on a slope less steep than four horizontal to one vertical (4H1V) are Type B if material would otherwise be classified as Type B.
- 8) Previously disturbed soils may be Type B unless they would be classed as Type C. Soil that meets requirements of Type A but is subject to vibration or fissured may be Type B by not that is not stable or soil that is part of a sloped tayered system where tayers dip into the excavation on a slope less sleep than four horizontal to one ventical (AHLTV) are Type B if material would otherwise be classified as type B.
- 9) Soil in a stopod layered system where layers dip into the excavation on a slope of four horizontal to one vertical (44: TV) or steeper may be Type C. Saturated soil or soils from which water is freely seeping but is not standing in the tench. Conditions more severe would require dewatering or the seating of the sides of the excavation and pumping the tench. Such severe conditions would require the services of a soils engineer to establish the design pressure. Consult the manufacturer for pressuresexceeding labulated values.
- 10) PRO-TEC shields are to be used in accordance with Federal, state and local tawa. Refer to Occupational Safety and Health Administration (OSHA) rules and regulations Vol. 54, No. 209, 10/31/69. Subpart P.
- 11) Shelds are for occupational safety use only. Dependent on specific size conditions, soil movement could occur. Affects on adjacent areas from potential soil movement shall be the responsibility of others.

Usage of shields other than specified could cause failure or cave-ins resulting in serious injury or death


Phone (517) 541-0303 - 1-800-292-1225 - Fax (517) 541-0329

Malling Address: P.O. Box 130 - Charlotte, MI 48813 - Shipping Address: 1298 Lipsey Drive - Charlotte, MI 48813

TAB DATA SHEET

3. The sides of the excavation shall be cut vertical and narrow to prevent lateral movement of the Manhole Shield. If necessary, backfill around the manhole shield to a height sufficient to prevent lateral movement.









Owner/Operator Manual

 Danger – Do not wear loose fitting clothing while operating this equipment.

 Danger – Deactivate operator controls when workers must enter swing radius area.





Closed Lifting Eye





DANGER



Unauthorized modification to the coupler and/or any coupler components may impair function, affect performance, and affect the life of the coupler, the excavator, and/or the attachment. Unauthorized modification may impair the safety of personnel and can cause serious injury or death. Hendrix assumes no responsibility for any unauthorized modifications to the coupler and/or coupler components. Unauthorized modification voids the coupler's warranty.



HENDRIX QUICX GOUPLER USER MANUAL

OPERATIONS & MAINTENANCE SECTION V - ENGAGING THE ATTACHMENT Continued....



DANGER



CONNECTION TESTS MUST BE PERFORMED EACH AND EVERY TIME YOU ENGAGE AN ATTACHMENT. FAILURE TO PROPERLY ENGAGE AN ATTACHMENT CAN RESULT IN SERIOUS INJURY OR DEATH. THE ATTACHMENT MAY DROP WITHOUT WARNING IF THE COUPLER IS NOT PROPERLY ENGAGED WITH THE ATTACHMENT.



DANGER



ENGAGE ATTACHMENTS COMPLETELY CLEAR OF ALL PERSONNEL.

TEST ALL CONNECTIONS AWAY FROM ALL PERSONNEL.

NEVER SWING COUPLED ATTACHMENTS OVER WORKERS' HEADS.


8. CONNECTION TEST ONE

Perform away from all personnel = Test the connection to the attachment by completely curing the couper inward (see Fig. 38-1).




7. CONNECTION TEST TWO

Perform away from all personnel - Test the connection by fully cycling the coupled attachment at least twice (see Fig. 38-2).



8. CONNECTION TEST THREE

Perform away from all personnel - Test the coupler connection by trying to disengage the attachment from the coupler using the machine's weight. Dig the attachment in the ground, lower the attachment against the ground to lift the excavator's tracks off the ground, and try to force the attachment off (see Fig. 38-3).



Connection Testing


- Attach Bucket
- Curl in
- Cycle Two Times
- Force Test



DEERATIONS & MAINTENANCE SECTION III - 1ST GENI Continued ...

E. MECHANICAL LOCK PIN (1st Generation)

Later model 1st Generation Hendris Quick Quickers are equipped with a mechanical locking pin. This pin is inserted behind the Locking Lever and is secured in place using tynch pins on each end of the pin. If you have a coupler that does not have a mechanical locking pin. Hendris recommends that you obtain and install the mechanical locking pin. Please contact your Hendris dealer for details.



END OF SECTION

Mechanical Locking Pin

Commitment

- Commitment
- Accountability

Management Principles

- Commitment
- Accountability
- Training

- Commitment
- Accountability
- Training
- Employee Involvement

- Commitment
- Accountability
- Training
- Employee Involvement
- Hazard Identification

Commitment

Accident Investigations

- Accountability
- Training
- Employee Involvement
- Hazard Identification

- Commitment
- Accountability
- Training
- Employee Involvement
- Hazard Identification

- Accident Investigations
- Program Review



Accident Investigator Models

Company		Description	In memoriam
1	Siemens	Wind turbine collapse	Chadd Mitchell
2	Wilkins Trucking	Crushed under truck	Glen Hibbert
3	Alcides Alfaro	Failure to apply brake	Pedro Sagasizado
4	Alpine Courier	Failure to apply brake	Mike Beyea
5	Tapani Underground	Failure to apply brake	Gen Stewart
6	Celorie Brothers	Crushed in semi-trailer door	Steve Kaufman
7	Valley View Logging	Brake failure	Louis "Tony" Wofford
8	Coral Construction	Power line contact	Luke Stinson
9	Patrick Gould Construction	Overloaded forklift	Noe Sanchez
10	Stalcup Roofing	Truss failure	Dewayne "Doug" Smith
11	J.L. Jersey	Crushed by rotating superstructure	Larry Fry
12	Williams & Ryan Construction	Crushed, object fell off quick coupler	Jeff Helgeson
13	M.L. Merrill Construction	Trench cave-in	Ed Manley
14	North Creek Recycling	Crushed by boom	Gerald Stierwaly
15	Oregon Mainline Paving	Crushed between outrigger and boom	David Lasley
16	J.L. Jersey	Rigging failure	David Johnston